Honing device and honing tool 039





First step:

Fix the honing device on the lathe or on a vertical drilling machine and fix the honing tool on the honing device



Second step:

Adjust the expansion and insert the part on the honing tool



Third step:

Move back and forth the part



Forth étape :

Measure the part and return to the second step if necessary

Typical use : rough machining and finishing of diameter, surface roughness improvement

Typical quantity : > 100 parts

Necessary equipment : lathe or drilling machine

To be used by : toolmaker, machining office, bar turner (Swiss machining), manufacturing of large batches